

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/26/2022

Submitted Date:

08/26/2022

Document Number:

699804863

FIELD INSPECTION FORMLoc ID 323785 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: 1660 LINCOLN STREET SUITE 1450

City: DENVER State: CO Zip: 80264

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Couts, Brandon		bcoutts@mustangresourcesllc.com	Field Operations
Lemon, Deb	303-807-5112	dlemon@mustangresourcesllc.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210803	WELL	PR	01/01/2018	GW	045-06561	YOUBERG 23-24-6S-94W	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday 8/24/22 at approximately 13:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at MUSTANG RESOURCES LLC YOUBERG-66S94W /23SES.W.

Location #323785 in Garfield County Colorado.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1) Domestic tap appears to be connected and in operation no form 44 on file with a corrective action date of 11/24/22.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No tank battery located on location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/888-291-8588

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on free flow no tools		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 210803 Type: WELL API Number: 045-06561 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Flowline

#1 Type: Non-Well Site

of Lines

Flowline DescriptionFlowline Type: Non-Well Site

Size:

Material:

Variance:

Age:

Contents:

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure Testing

Witnessed:

Test Result:

Charted:

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☐ 1102. Operations, Maintenance, and Repair☐ 1103. AbandonmentComment: Domestic tap appears to be connected and in operation no form 44 on file.

Corrective Action:

Within 90-days of installation or discovery of a domestic tap connected to the operator's flowline, an operator must submit a Flowline Report, Form 44, to the Director to register the tap.Date: 11/24/2022

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Compaction						
		Gravel				
Gravel						
		Berms				
Ditches						
		Compaction				

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Flowlines for corrective actions.	depaoloc	08/26/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699804864	Photos for Insp. #699804863	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5841094