

FORM  
INSPRev  
X/20

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/25/2022

Submitted Date:

08/29/2022

Document Number:

696204012

### FIELD INSPECTION FORM

Loc ID 322318 Inspector Name: Trujillo, Aaron On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 22370  
Name of Operator: D & G ROUSTABOUT SERVICE  
Address: 765 S 1/2 ROAD  
City: MACK State: CO Zip: 81525

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 4 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		terrelloil@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
322318	LOCATION	AC			-	WEST SALT CREEK-FEDERAL-66S103W 7NESW	RI

**General Comment:**

On 8/25/2022, Reclamation Specialist Trujillo inspected D & G ROUSTABOUT SERVICEs West Salt Creek-Federal 1-7 Location in Garfield County, Colorado.

The following compliance issues were observed during this inspection:

- Equipment, weeds, waste and trash requirements
- Secondary containment

Refer to the "Location" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	<p>Previous inspection observed Undesirable weedy plant species observed establishing on the working pad areas of the Location, and around the production equipment, including wellhead; this is considered a fire hazard. Noxious weeds (Bindweed) also observed establishing on the Location. Inspection required Operator to comply with Rules 606 and 1003.f.</p> <p>It was observed in this inspection that work to prevent further spread and establishment of weeds on the Location, and around production equipment has been insufficient; Undesirable and Noxious weeds have continued to establish; vegetation around production equipment has continued to establish.</p>		
Corrective Action:	<p>Comply with Rule 606 and Rule 1003.f. Implement BMPs to prevent further spread and establishment of weeds on the Location, and to prevent weed/plant establishment around production equipment.</p>		Date: <u>09/13/2022</u>

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	STEEL AST		,
Comment:	50 bbl Produced water				
Corrective Action:					Date:

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth		Walls Insufficient	Base Insufficient	Inadequate
Comment:	<p>Previous inspection observed vegetation established within the base and walls of the secondary containment, rendering the permeability of the containment insufficient; vegetation establishment compromises the integrity and permeability of the containment BMP.</p> <p>It was observed in this inspection that work to ensure containment remains impervious, and to prevent vegetative establishment at the BMP is inadequate; vegetation has re-established on and within the BMP.</p>			

Corrective Action:	Maintain BMP to ensure containment integrity is not compromised; remove vegetation established within base, and on walls, of the containment BMP. Ensure containment is sufficient to contain 150% of the volume of the tank.	Date:	09/13/2022
--------------------	---	-------	------------

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 322318 Type: LOCATION API Number: - Status: AC Insp. Status: RI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696204013	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5842205">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5842205</a>