

Inspection Photos  
Location Name: Dowler 1B  
Location ID: 307008



IMG 01  
Well sign



IMG 02  
Impacted material



**IMG 03**  
**Impacted material**



**IMG 04**  
**Impacted material**



**IMG 05**

**Lube oil/produced water**