

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/29/2022

Submitted Date:

08/29/2022

Document Number:

702500355**FIELD INSPECTION FORM**Loc ID 312052 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|---------------------------------------|--------------------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| , General | | FarmingtonRegulatoryTechs@hilcorp.com | All SW field inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 216500 | WELL | PR | 01/01/2003 | CBM | 067-08106 | ANIMAS 34-10 36-1 | PR |
| 297003 | WELL | PR | 02/01/2011 | CBM | 067-09593 | ANIMAS 34-10 36-1A | PR |
| 297004 | WELL | PR | 05/01/2021 | CBM | 067-09594 | ANIMAS 34-10 36-2A | PR |

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

Lube oil at 1A wellhead has impacted surface material (IMG 03).

Corrective Action:

Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.

Date: 09/13/2022

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type

OTHER

Comment:

Pump jacks and plunger lift wellhead are enclosed by stock panel.

Corrective Action:

Date:

Equipment:

corrective date

Type: Flow Line

7

Comment:

3 4" lines from wellheads to separators, 2 1" lines from separator to gas powered prime movers, line from separator to produced water off location, 1" line from separator to plunger lift wellhead is out of service and is locked out tagged out.

Corrective Action:

Date:

Type: Pump Jack

2

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

8

Comment:

Corrective Action:

Date:

Type: Bird Protectors

1

Comment:

Separator vent stack is screened properly.

Corrective Action:

Date:

Type: Other

1

Comment:

Lube oil at 2A wellhead does not have spill prevention (IMG 04).

Corrective Action:

Implement or modify BMPs for improved material handling and spill prevention per rule 1002.f.(2)B.

Date: 09/13/2022

Type: Gas Meter Run

3

Comment:

Gas meter calibrations are within the last year.

Corrective Action:

Date:

| | | | |
|---------------------------------|---|-------|--|
| Type: Bradenhead | # 3 | | |
| Comment: | Bradenheads are accessible. | | |
| Corrective Action: | | Date: | |
| Type: Compressor | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 2 | | |
| Comment: | Gas powered prime mover | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 4 | | |
| Comment: | Telemetry, solar panels, cathodic protection, valve pit | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 216500 Type: WELL API Number: 067-08106 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 297003 Type: WELL API Number: 067-09593 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 297004 Type: WELL API Number: 067-09594 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Gravel | Pass | | | |
| | | Compaction | Pass | | | |
| Compaction | Pass | | | | | |
| Gravel | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 702500356 | Photo doc | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5842393 |