

GMT Exploration Company LLC, Irwin 6-65 23-11 10 HN  
039-06722  
Inspection #688313004  
8/25/2022  
Flowback Inspection



Colorado Oil and Gas Conservation Commission  
39.50842, -104.62569, 6236.9ft, 291°  
08/25/2022 01:28:35 PM



Colorado Oil and Gas Conservation Commission  
39.50989, -104.62585, 6072.8ft, 147°  
08/25/2022 01:55:23 PM





Colorado Oil and Gas Conservation Commission  
39.50981, -104.62565, 6148.3ft, 131°  
08/25/2022 01:48:09 PM





Colorado Oil and Gas Conservation Commission  
39.50982, -104.62568, 6177.8ft, 235°  
08/25/2022 01:48:46 PM





Colorado Oil and Gas Conservation Commission  
39.51011, -104.62667, 6187.7ft, 138°  
08/25/2022 01:52:46 PM





Production facility under construction on the pad.

Colorado Oil and Gas Conservation Commission

39.50977, -104.62567, 6112.2ft, 74°

08/25/2022 01:47:53 PM





Colorado Oil and Gas Conservation Commission  
39.50979, -104.62566, 6128.6ft, 347°  
08/25/2022 01:48:00 PM





Silt/frog fence is  
down.

Colorado Oil and Gas Conservation Commission  
39.51014, -104.62668, 6204.1ft, 291°  
08/25/2022 01:51:59 PM



Colorado Oil and Gas Conservation Commission  
39.51016, -104.62668, 6177.8ft, 229°  
08/25/2022 01:52:07 PM