

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/29/2022

Submitted Date:

08/30/2022

Document Number:

702500353

FIELD INSPECTION FORM

Loc ID 333517 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10734
Name of Operator: HIGH RIVER RESOURCES OPERATING LLC
Address: 3838 OAK LAWN AVE SUITE 710
City: DALLAS State: TX Zip: 75219

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Archuleta, Amy		aarchuleta@highriverllc.com	All Inspections
Vaughn, Robert		rvaughn@highriverllc.co	Primary Contact

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214279	WELL	PR	10/01/2019	GW	067-05614	BONDAD 34-10 1-36	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type DEBRIS

Comment: Broken pipe wrench handle and round metal plate near 2" flow line (IMG 03).

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type OTHER

Comment: Produced water tank enclosed by mesh fencing.

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Horizontal Heated Separator # 2

Comment:

Corrective Action:

Date: _____

Type: Ancillary equipment # 1

Comment: Telemetry

Corrective Action:

Date: _____

Type: Compressor # 1

Comment:

Corrective Action:

Date: _____

Type: Flow Line # 4

Comment: 2" line from wellhead to separator, line from separator to produced water, 2" line from gas meter run to off location, 3/4" line at gas meter run

Corrective Action:

Date: _____

Type: Bird Protectors # 2

Comment: Separator vent stack is screened properly

Corrective Action:

Date: _____

Type: Deadman # & Marked # 4

Comment:

Corrective Action:

Date: _____

Type: Gas Meter Run # 2

Comment:	Gas meter calibration is within the last year.	Date:	
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.	Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PBV STEEL		37.144798,-107.881225
Comment:	Partially buried produced water tank with steel mesh top.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	20 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV STEEL		37.144610,-107.881429
Comment:	Partially buried produced water tank with steel mesh top.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	60 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Hole in metal secondary containment (IMG 04).			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).			
				Date: 09/29/2022

Venting:

Yes/No		Date:	
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
------	--

Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 214279 Type: WELL API Number: 067-05614 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	
		Gravel	Pass			
Compaction	Pass					
Gravel	Pass					
		Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500354	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5842913