

Construction and Stormwater Inspection

August 10, 2022

Operator: NOBLE ENERGY INC- #100322

Location ID: 459556

Inspection Document #: 697504136

Weld County, CO

NWNW Section 29 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: C29-04 /Pad
Location ID: 459556



Photo 1. Photo taken from the entrance of location, facing Southwest. Photo illustrates a cattle guard which would also serve as a VTC device BMP. Also, filtrex has been installed around the entire perimeter of location.



Photo 2. Photo taken from the entrance of location, facing South. Photo illustrates the stabilized outlet of the culvert which is directed to a sediment basin.

Inspection Photos
Location Name: C29-04 /Pad
Location ID: 459556



Photo 3. Photo taken from the northeastern location, facing West. Photo illustrates the eastern sediment basin area which has been seeded, straw crimped with mulch and tackifier applied.



Photo 4. Photo taken from the northern location, facing West. See comments under Photo 3.

Inspection Photos
Location Name: C29-04 /Pad
Location ID: 459556



Photo 5. Photo taken from the weir of the outlet structure, facing Northwest. Photo illustrates the riprap material has been buried.



Photo 6. Photo taken from the western location, facing Southwest. See comments under Photo 3.

Inspection Photos
Location Name: C29-04 /Pad
Location ID: 459556



Photo 7. Photo taken from the southwestern location, facing Southeast. See comments under Photo 3.



Photo 8. Photo taken from the eastern location, facing East. Photo illustrates the topsoil stockpile which has been stabilized with seeding, straw crimped with mulch and tackifier applied.

