

Location

Overall Good:

Signs/Marker:

Type	DRILLING/RECOMP		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 442024 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Well Drilling

Rig: Rig Name: Ensign 161 Pusher/Rig Manager: Auther
Permit Posted: SATISFACTORY Access Sign: SATISFACTORY

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
Pressure Test BOP: Pass Test Pressure PSI: 1538 Safety Plan: YES

Drill Fluids

Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
Multi-Well: _____ Disposal Location: Buffalo Ridge - Keenesburg

Comment: Current Well: Faherty 13-5-3
Setting Production Casing
Total Depth: 12, 270'
Rig Currently using Open Candle Stick Flare

Corrective Action: Comply with Rule 903.b.(3)

Date: 09/05/2022

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Ditches		Gravel		Covering Materials		
Waddles						
Seeding						
Retention Ponds						
				Material Handling And Spill Prevention		

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine Driling Inspection	petrie	08/30/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696304409	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5843459