

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/30/2022

Submitted Date:

08/31/2022

Document Number:

702500365

FIELD INSPECTION FORMLoc ID 325498 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 25250

Name of Operator: DUGAN PRODUCTION CORP

Address: P O BOX 420

City: FARMINGTON State: NM Zip: 87499-

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

18 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Armenta, Bill	505-325-1821	billarmenta@duganproduction.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Alexander, John		john.alexander@duganproduction.com	All SW Inspections
Smaka, Kevin	505-325-1821	kevin.smaka@duganproduction.com	Sw Insp Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214894	WELL	PR	02/28/2011	GW	067-06498	TIFFANY 1	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Fuel container (IMG 05), muffler hose by southern separator (IMG 04), and muffler hose by north produced water tank (IMG 09) are unused equipment.		
Corrective Action:	All unused equipment must be returned to use or stored off location per rule 606. Ensure within 25' of wellhead, tanks, and separators are free of combustible material per rule 610.k		Date: 09/14/2022
Type	OTHER		
Comment:	Lube oil from compressor skid has impacted surface materials (IMG 06).		
Corrective Action:	Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.		Date: 09/14/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Northern separator and produced water tank are enclosed by metal safety fence, southern produced water tank enclosed by wire fencing.		
Corrective Action:		Date:	

Equipment:

		corrective date
Type: Gas Meter Run	# 1	
Comment:	Gas meter run is off location. Gas meter calibration is within the last year.	
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment:	Telemetry, cathodic protection, solar panel on north edge of location.	
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:
Type: Compressor	# 1	
Comment:	Compressor skid	
Corrective Action:		Date:
Type: Flow Line	# 5	

Comment: 2" line from wellhead to northern separator, line from northern separator to northern produced water tank, 2" line from northern separator to southern separator, 2" line from northern separator to northern produced water tank, 4" line from southern separator to gas meter run off location. 3/4" flow line near southern edge of location is not in use and is not locked out/tagged out.			
Corrective Action: Apply Out of Service Locked and Tagged on unused flow line per rule 1101.(3)		Date:	09/02/2022
Type: Bird Protectors	# 2		
Comment: Separator vent stacks are screened properly.			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment: Bradenhead is accessible.			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	OTHER		37.035734,-107.581454
Comment: Above ground produced water tank.					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	45 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Compacted gravel earth berm					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	OTHER		37.036016,-107.581546
Comment: Above ground produced water tank.					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	50 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate	
Comment:	Diminished berm height on eastern edge of secondary containment (IMG 10).				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date:	09/30/2022

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 214894	Type: WELL	API Number: 067-06498	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Fail			
				Material Handling And Spill Prevention	Pass	
Gravel	Fail					
Compaction	Fail					
		Compaction	Fail			

Comment: [Access road and location have developed ruts up to 12" deep \(IMG 07 and IMG 08\). Similar conditions were observed in previous inspections Doc# 693900807 and Doc# 687905647.](#)

Corrective Action: [Maintain access road and location conditions per rule 1002.f\(2\)F. Emergency vehicles must be able to access location in inclement weather conditions.](#)

Date: 09/16/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500366	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5844438