

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/23/2022

Submitted Date:

08/25/2022

Document Number:

700600410**FIELD INSPECTION FORM**Loc ID 324788 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 16520Name of Operator: CHEMCO INCAddress: 6970 SOUTH HOLLY CIR STE 206City: CENTENNIAL State: CO Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Neher, Morgan	303-771-7777	morgan@chemco-og.com	
Costa, Ryan		ryan.costa@state.co.us	
Neher, Gray		gh.neher@chemco-og.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
100862	PIT		09/23/1999		-	STUBBS 1	
212602	WELL	PR	06/01/2020	OW	061-05055	STUBBS 1	PR

General Comment:

Historic produced water pit area is not growing vegetation. See attached photos and aerial images. Operator shall submit Form 27 Remediation Plan to investigate potential soil impacts hindering vegetation growth.

Inspected Facilities									
Facility ID:	100862	Type:	PIT	API Number: -	Status:		Insp. Status:		
Facility ID:	212602	Type:	WELL	API Number:	061-05055	Status:	PR	Insp. Status:	PR

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: ☐Pit ID: 100862Lat: 38.409692Long: -102.452534Reference Point: SEOther: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Pit has been closed but surface reclamation is inadequate. See attached images and aerial photos.Corrective Action: Submit Form 27 Remediation Plan to investigate soil impacts impeding vegetation growth.Date: 09/09/2022**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: ☐Oil Accumulation: ☐2+ feet Freeboard: ☐Comment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403146654	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5839555
700600411	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5839551
700600412	GoogleEarthAerialMap	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5839552
700600413	COGCCaerialimage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5839553