

Inspection Photos

August 29, 2022

Operator: Antler Energy LLC - #10407

Location ID: 313077

Location Name: Sand Hills Federal-611N91W /15SWSW

Inspection Document #: 702800630

Moffat County, CO

SWSW Section 15 T11N R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Sand Hills Federal-611N91W /15SWSW

Location ID: 313077



Photo 1. Photo taken from the southwest shows an overview of the working pad area.



Photo 2. Photo shows stained soils.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800630

Inspection Photos

Location Name: Sand Hills Federal-611N91W /15SWSW

Location ID: 313077



Photo 3. Photo shows stained soils adjacent to the pump house and produced water tanks.



Photo 4. Photo shows stained soils adjacent to the produced water tanks.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800630

Inspection Photos
Location Name: Sand Hills Federal-611N91W /15SWSW
Location ID: 313077



Photo 5. Photo shows stained soils at load lines.



Photo 6. Refer to Photo 5 comment.



Inspection Photos

Location Name: Sand Hills Federal-611N91W /15SSSW

Location ID: 313077




Photo 7. Photo taken from the north of the Location shows a bull thistle (List B Noxious) plant which has gone to seed.



Photo 8. Photo taken adjacent to the pump shed shows Canada thistle (List B Noxious) plants which have gone to seed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800630

Inspection Photos
Location Name: Sand Hills Federal-611N91W /15SWSW
Location ID: 313077



Photo 9. Photo taken from the southwest of the Location shows the topsoil stockpile is bare and unprotected.



Photo 10. Photo taken from the southwest of the Location shows the topsoil stockpile is bare and unprotected. Rill erosion is occurring.