

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/30/2022

Submitted Date:

08/30/2022

Document Number:

695106693**FIELD INSPECTION FORM**Loc ID 308630 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10758Name of Operator: OGRIS OPERATING LLCAddress: PO BOX 53467City: MIDLAND State: TX Zip: 79710**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
WARD, GIENA		gward@ogrisop.com	All Inspections
GEE, GREG	903-987-0353	ggee@ogrisop.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277394	WELL	PR	08/18/2009	CBM	071-08367	HILL RANCH 6-15	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bradenhead

1

Comment:

IS ACCESSABLE

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 277394 Type: WELL API Number: 071-08367 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 04/19/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: YESPit ID: 292564Lat: 37.020730Long: -104.926900

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition: Adequate

Comment:

Corrective Action

Date:

Fencing:Fencing Type: Netting/Fence comFencing Condition: Inadequate

Comment:

PHOTO 4: ELECTRIC FENCE AROUND PRODUCTION WATER PIT IS IN DISREPAIR.

Corrective Action

Comply with the fencing requirements per the 1002a rules.Date: 09/30/2022**Netting:**Netting Type: Fence/Net ComboNetting Condition: Good

Comment:

Corrective Action

Date:

Anchor Trench Present: YESOil Accumulation: NO2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

Permit:	Facility ID	Permit Num	Expiration Date
	292564	2059077	

COGCC Comments

Comment	User	Date
<u>THIS IS A FOLLOW UP TO INSP. DOC #690201275, PUMP WAS NOT RUNNING AT TIME OF INSPECTION SO IT WAS NOT LEAKING. SEE PIT SECTION OF THIS INSPECTION FOR DETAILS ON FENCING CORRECTIVE ACTION.</u>	beardslt	08/30/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695106694	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5849700