


Inspection Photos
Location Name: Herrera Gas Unit B 5
Location ID: 311913



IMG 01
Well sign




IMG 02
Location overview



IMG 03
Location overview



IMG 04
Impacted material



IMG 05
Impacted material



IMG 06
Tank sign



IMG 07

Erosion channel