

Inspection Photos  
Location Name: Crigler MVRD Unit 1  
Location ID: 333914



IMG 01  
Well sign



IMG 02  
Location overview

WGS84 37.09392,  
±12ft -107.72586



ft 6798  
±20ft



°T SW239  
±12

DATE	CALIBRATED YES / NO	GAS SAMPLE TYPE	BOTTLE #	ORIFICE OUT	ORIFICE IN	SPECIFIC GRAVITY	INSPECTED BY COMPANY
6/14/18	X	SPOT	#6210	1.000 -5/0-	1.000	0.5948	Aaron Estrada
9/20/19		SPOT	#4201		1.000	0.5963	Aaron Estrada
12/20/18	X	Spot	6249	SHARP 1.000	DIRTY 1.000	0.5955	ADRIAN VELARDE (Jude Sales)
3/20/19	y	SPOT	#6113	1.000	0.625	0.5952	Aaron Estrada
9/30/19	y	SPOT	#5012		-5/c- 0.625	0.5968	Aaron Estrada
1/21/2020	YES	SPOT	#4097		C/S 0.625	0.5960	EDDIE CHAVEZ
9/22/2020	YES	SPOT	#6081	SHARP + GWD →	0.625	0.5960	Aaron Estrada
10/21/2020	NO	SPOT	6148	N/A	N/A	N/A	ADRIAN VELARDE
1/20/21	YES	SPOT	#6128		-5/0- 0.625	N/A	Aaron Estrada

IMG 03  
Calibration card



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

13Sep22 10:22 Ad-hoc

4646 CR-318, Ignacio CO 81137, US © 13-Sep-22 10:22:13