

Inspection Photos

API: 009-06268

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 9/13/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06268 | Date: 9/13/2022

Inspection Photos



Photo 1. Facing east toward the tank battery along the access road. There is tall undesirable weeds around the tank that need to be removed. If take is not in use it must be removed. Tank berm is inadequate.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06268 | Date: 9/13/2022

Inspection Photos



Photo 2. The sign at the tank does not reflect current Operator or emergency contact INFO.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06268 | Date: 9/13/2022

Inspection Photos



Photo 3. The netting at the top of the tank is inadequate.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06268 | Date: 9/13/2022