

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/08/2022

Submitted Date:

09/08/2022

Document Number:

702500416

**FIELD INSPECTION FORM**

Loc ID 326167 Inspector Name: Klink, Alex On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 13 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name     | Phone | Email                         | Comment                                  |
|------------------|-------|-------------------------------|--|
| , General        |       | sjninspections@ikavenergy.com | <a href="#">All SW field inspections</a> |
| Labowskie, Steve |       | steve.labowskie@state.co.us   |  |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 215984      | WELL | PR     | 12/08/1990  | CBM        | 067-07590 | THOMAS JACQUEZ E 1 | PR          |

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | WEEDS   |       |            |
| Comment:           | Weeds near produced water tank and compressor. (IMG 03 and IMG 04)  |       |            |
| Corrective Action: | Control weeds per rule 606.<br><br>Ensure within 25' of wellhead, tanks, and separators are free of combustible material per rule 610.k   | Date: | 09/17/2022 |
| Type               | STORAGE OF SUPL   |       |            |
| Comment:           | Stairs at produced water are not in use (IMG 05). Unused sack of material is deteriorated and unused (IMG 06), traffic marker and base are not in use (IMG 07 and IMG 08), barrel with broken headphones and wires (IMG 09) are unused. |       |            |
| Corrective Action: | All unused equipment must be returned to use or stored off location per rule 606.   | Date: | 09/17/2022 |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               | OTHER  |       |  |
| Comment:           | Location enclosed by chain link fence with barbed wire, compressor enclosed by sound panel, produced water tank enclosed by sound panel. |       |  |
| Corrective Action: |  | Date: |  |

**Equipment:**

| Type                              |  |       | corrective date |
|-----------------------------------|--|-------|-----------------|
| Type: Bird Protectors             | # 2  |       |                 |
| Comment:                          | All vents are screened.  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Vertical Heated Separator   | # 1  |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Horizontal Heated Separator | # 1  |       |                 |
| Comment:                          |  |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Gas Meter Run               | # 1  |       |                 |
| Comment:                          | Gas meter calibration is within the last year.                             |       |                 |
| Corrective Action:                |  | Date: |                 |
| Type: Ancillary equipment         | # 4  |       |                 |
| Comment:                          | Telemetry, valve pit cluster, produced water transfer pump, electric house |       |                 |

|                    |   |       |  |
|--------------------|---|-------|--|
| Corrective Action: |   | Date: |  |
| Type: Compressor   | # 1   |       |  |
| Comment:           |   |       |  |
| Corrective Action: |   | Date: |  |
| Type: Other        | #   |       |  |
| Comment:           | Chemical containers with spill prevention.<br>Lube oil within secondary containment is nearly full (IMG 10).  |       |  |
| Corrective Action: |   | Date: |  |
| Type: Bradenhead   | # 1   |       |  |
| Comment:           | Bradenhead is accessible.   |       |  |
| Corrective Action: |   | Date: |  |
| Type: Flow Line    | # 6   |       |  |
| Comment:           | 6" line from wellhead to separator, 6" line from separator to compressor, 6" line from compressor to gas meter run, 6" line from gas meter run to off location, line from separator to produced water. 1" line at produced water tank battery |       |  |
| Corrective Action: |   | Date: |  |

**Tanks and Berms:**

| Contents           | #  | Capacity | Type  | Tank ID | SE GPS                |
|--------------------|--|----------|-------|---------|-----------------------|
| PRODUCED WATER     | 1  | 400 BBLs | OTHER |         | 37.103135,-107.897960 |
| Comment:           | 2 above ground produced water tanks each with 400 bbl capacity |          |       |         |                       |
| Corrective Action: |  |          |       |         | Date:                 |

Paint

|                  |              |
|------------------|--------------|
| Condition        | Adequate     |
| Other (Content)  |              |
| Other (Capacity) | 400 bbl each |
| Other (Type)     |              |

Berms

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | #                               | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---------------------------------|----------|-----------|---------|-----------------------|
| PRODUCED WATER     | 1                               | <50 BBLs | PBV STEEL |         | 37.103399,-107.898655 |
| Comment:           | Partially buried produced water |          |           |         |                       |
| Corrective Action: |                                 |          |           |         | Date:                 |

Paint

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) | 21 bbl   |
| Other (Type)     |          |

Berms

|                    |          |                     |                     |             |  |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |  |
| Earth              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |  |
| Comment:           |          |                     |                     |             |  |
| Corrective Action: |          |                     |                     | Date:       |  |

**Venting:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Yes/No             |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 215984 Type: WELL API Number: 067-07590 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Compaction       | Pass            |                         |                       |  |                          |         |
|                  |                 |                         |                       | Material Handling And Spill Prevention | Pass                     |         |
|                  |                 | Gravel                  | Pass                  |  |                          |         |
| Gravel           | Pass            |                         |                       |  |                          |         |
| Ditches          | Pass            |                         |                       |  |                          |         |
| Berms            | Pass            |                         |                       |  |                          |         |
|                  |                 | Compaction              | Pass                  |  |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403160293    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5851720">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5851720</a> |
| 702500417    | Photo doc            | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5851715">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5851715</a> |