

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /4NENW

Location ID: 334832



Photo #7655 From entrance to location.



Photo #7656 Unused equipment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /4NENW

Location ID: 334832



Photo #7658 Loadline open ended.



Photo #7659 Run on to location is not being controlled.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /4NENW

Location ID: 334832



Photo #7660 Run on to location is not being controlled.



Photo #7661 Sediment is encroaching on equipment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /4NENW

Location ID: 334832



Photo #7662 Rill erosion occurring on cut slope.



Photo #7663 Rill erosion occurring on cut slope.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /4NENW

Location ID: 334832



Photo #7665 Sediment encroaching on equipment.