

Inspection Photos

API: 009-06603

Operator: ENERGY ALLIANCE COMPANY INC

Inspection Date: 9/13/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06603 | Date: 9/13/2022

Inspection Photos



Photo 1. There is a piper riser that still remains along the flowline 1770' east of the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06603 | Date: 9/13/2022

Inspection Photos



Photo 2. Center of the location facing north.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06603 | Date: 9/13/2022

Inspection Photos



Photo 3. Center of the location facing south.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06603 | Date: 9/13/2022