

Inspection Photos

API: 009-06124

Operator: ENERVEST OPERATING LLC

Inspection Date: 9/13/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06124 | Date: 9/13/2022

Inspection Photos



Photo 1. Center of the location facing north. The location has been fenced and it appears decompaction and seeding was performed. Perennial vegetation has not yet established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06124 | Date: 9/13/2022

Inspection Photos



Photo 2. Center of the location facing south.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06124 | Date: 9/13/2022

Inspection Photos



Photo 3. Center of the location facing west.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06124 | Date: 9/13/2022

Inspection Photos



Photo 4. Center of the location facing east.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06124 | Date: 9/13/2022

Inspection Photos



Photo 5. View of ground cover shows some vegetation beginning to establish. Additional growing season and maintenance will be needed to fully establish vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06124 | Date: 9/13/2022