

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/09/2022

Submitted Date:

09/09/2022

Document Number:

702500421

FIELD INSPECTION FORM
 Loc ID 333603 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 25250

Name of Operator: DUGAN PRODUCTION CORP

Address: P O BOX 420

City: FARMINGTON State: NM Zip: 87499-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Feil, Tyra		tyrafeil@duganproduction.com	SW Field inspections
Alexander, John		johncalexander@duganproduction.com	SW Inspections
Wheeler, Cody		Cody.Wheeler@duganproduction.com	SW Field inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Smaka, Kevin	505-325-1821	kevin.smaka@duganproduction.com	Sw Insp Reports
Heslop, Jason		Jason.Heslop@duganproduction.com	SW Field inspections
Foutz, Marty		marty.foutz@duganproduction.com	SW inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214890	WELL	PR	01/05/2022	GW	067-06494	ANIMAS 1	PR
261072	WELL	PR	09/01/2017	CBM	067-08517	ANIMAS 36-2	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Muffler hose is unused (IMG 03), and fuel container is unused with no spill prevention (IMG 04).		
Corrective Action:	All unused equipment must be returned to use or stored off location per rule 606.		Date: 09/24/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Produced water tanks are enclosed by wire fencing		
Corrective Action:			Date:

Equipment:

Type: Horizontal Heated Separator	# 2		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration is within the last year.		
Corrective Action:			Date:
Type: Flow Line	# 4		
Comment:	2" from wellhead to separator, 2" from separator to secondary separator, 2" to compressor, line from separator to produced water.		
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		

Comment:	separator vent stacks are screened properly.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER		<50 BBLS	PBV STEEL		,	
Comment:	Partially buried produced water tank. Paint is deteriorating					
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)	45 bbl				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Earth berm with liner.				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,	
Comment:	Partially buried produced water tank.					
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)	80 bbl				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type			
Comment:			
Corrective Action:			
		Date:	

Inspected FacilitiesFacility ID: 214890 Type: WELL API Number: 067-06494 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 261072 Type: WELL API Number: 067-08517 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					
Gravel	Pass					
Ditches	Pass					
Compaction	Pass					
Rip Rap	Pass					
Berms	Pass					
		Check Dams	Pass			
Waddles	Pass					
		Gravel	Pass			
				Material Handling And Spill Prevention	Pass	
		Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403161282	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5852727
702500422	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5852722