

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/12/2022

Submitted Date:

09/12/2022

Document Number:

702500427

FIELD INSPECTION FORM
 Loc ID 326615 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259209	WELL	PR	06/13/2001	CBM	067-08403	ARTHUR MASON A 2	PR
412490	WELL	PR	10/15/2021	GW	067-09763	ARTHUR MASON A 4	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well sign is deteriorated (IMG 01).		
Corrective Action:	Install sign to comply with Rule 605.a.		Date: 10/12/2022
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tan sign not secured properly (IMG 05).		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 11/12/2022

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Pipe fittings are not in use (IMG 07 and IMG 08).		
Corrective Action:	All unused equipment must be returned to use or stored off location per rule 606.		Date: 09/28/2022
Type	WEEDS		
Comment:	Weeds near produced water tank and separator (IMG 06).		
Corrective Action:	Ensure within 25' of wellhead, tanks, and separators are free of combustible material per rule 610.k		Date: 09/21/2022
Type	OTHER		
Comment:	Impacted material at A 4 wellhead (IMG 03).		
Corrective Action:	Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.		Date: 09/28/2022
Type	STORAGE OF SUPL		
Comment:	Landowner appears to be storing agricultural equipment on edge of location (IMG 04).		
Corrective Action:			Date:

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Equipment at this facility is enclosed by stock panel.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Flow Line	# 6		
Comment:	2 3" and 2 2" lines from wellheads to separators, line from separators to produced water, 4" line from gas meter run to off location.		
Corrective Action:			Date:

Type: Bradenhead	# 1		
Comment:	Bradenheads are accessible.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	Telemetry, electric cabinet, valve cluster pit, 2 pump control panels,		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Gas meter calibrations are up to date.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	tank vent stack is screened properly.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Linear rod pump		
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Electric		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.176508,-107.855286	
Comment:	Partially buried produced water tank.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl	
Other (Type)	cone top	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Double walled tank.			
Corrective Action:				Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 259209 Type: WELL API Number: 067-08403 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 412490 Type: WELL API Number: 067-09763 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Gravel	Pass					
		Gravel	Pass			
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403162928	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5857408
702500428	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5857392