

Inspection Photos

API: 071-07862

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07862 | Date: 9/16/2022

Inspection Photos



Photo 1. Facing north along the access road. Stormwater is bypassing the culvert causing erosion down the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07862 | Date: 9/16/2022

Inspection Photos



Photo 2. Facing back down the road. There is erosion along the road side that needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07862 | Date: 9/16/2022

Inspection Photos



Photo 3. Further up the road is a culvert where stormwater is bypassing. This needs to be dug out to allow stormwater flow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07862 | Date: 9/16/2022

Inspection Photos



Photo 4. Facing southwest toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07862 | Date: 9/16/2022

Inspection Photos



Photo 5. There are 3 pipe risers with no OOSLAT.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07862 | Date: 9/16/2022

Inspection Photos



Photo 6. Well sign is posted at the meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07862 | Date: 9/16/2022