

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/20/2022

Submitted Date:

09/20/2022

Document Number:

702500452**FIELD INSPECTION FORM**Loc ID 311950 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Overright, Issac		ioverright@maralexinc.com	All SW field inspections
Harrison, Trish	970 759 9545	trishharrison@eis-llc.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216433	WELL	PR	08/14/2002	CBM	067-08039	MOLLIE CORYNNE 33-7-2 1	PR
294236	WELL	PR	01/08/2008	CBM	067-09474	MOLLIE CORYNNE 33-7-2 3B	PR

General Comment:

Inspector Alex Klink on site to conduct follow up inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	CA from previous inspection Doc# 702500237 has been satisfactorily completed.		
Corrective Action:		Date:	
Type	WEEDS		
Comment:	Weeds at wellhead (IMG 03).		
Corrective Action:	Ensure within 25' of wellhead, tanks, and separators are free of combustible material, including weeds, per rule 610.k	Date:	09/29/2022
Type	OTHER		
Comment:	CA regarding impacted material from previous inspection Doc# 702500237 has been satisfactorily completed.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Prime Mover	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 10		
Comment:	2 2" lines from wellheads to separators, 2 2" produced water lines from separators to off location, 2 1" lines from separator to gas powered prime mover, 2 2" lines from separator to gas meter run, 2 3" lines from gas meter run to off location.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	CA from previous inspection Doc# 702500237 has been satisfactorily completed.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 2		

Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 216433 Type: WELL API Number: 067-08039 Status: PR Insp. Status: PR

BradenHead

Date of Last Brhd Test: 07/20/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: CA from previous inspection Doc# 702500237 has been satisfactorily completed.

Corrective Action:

Date:

Workover

Comment: No Form 42 for MIRU is on file for workover rig.

Corrective Action: Submit Form 42 for MIRU 48 hours in advance for planned operations, or within 24 hours of commencement of unplanned operations per rule 405.e.

Date: 09/28/2022

Facility ID: 294236 Type: WELL API Number: 067-09474 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/21/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: CA from previous inspection Doc# 702500237 has been satisfactorily completed.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500453	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5865435