

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/20/2022

Submitted Date:

09/20/2022

Document Number:

702500454

FIELD INSPECTION FORM

 Loc ID 325477 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____
Operator Information:

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

2 Number of Corrective Actions

- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Overright, Issac		ioverright@maralexinc.com	All SW field inspections
Harrison, Trish	970 759 9545	trishharrison@eis-llc.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214856	WELL	PR	06/01/2022	GW	067-06460	MAGDALEN CLARE 33-7-2 2	PR

General Comment:

Inspector Alex Klink on site to conduct follow up inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Capacity not listed on produced water tank sign (IMG 04). CA from previous inspection Doc# 702500235 has not been completed. Original CA date remains to document non compliance.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	07/30/2022

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds at wellhead (IMG 02), weeds at separator (IMG 03), and weeds at produced water tank (IMG 05).		
Corrective Action:	Ensure within 25' of wellhead, tanks, and separators are free of combustibile material, including weeds, per rule 610.k	Date:	09/29/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 214856 Type: WELL API Number: 067-06460 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/21/2022 Annual Brhd Completed?

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: CA from previous inspection Doc# 702500235 has been satisfactorily completed.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500455	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5865436