

Final Reclamation and Stormwater Inspection

Date: 09/14/2022

Operator: PRIME OPERATING COMPANY - 72118

Location ID: 337340

Inspection Document #: 696105430

Yuma County, CO

NESW Section 2 T5S R44W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: EVANS #11-2-1
Location ID: 337340



Photo 1. Taken from beginning of access road, facing north. Photo illustrates access road has not been reclaimed or revegetated to reflect reference areas; annual weedy vegetation is predominantly russian thistle.

Inspection Photos
Location Name: EVANS #11-2-1
Location ID: 337340



Photo 2. Access road facing north. Photo illustrates road has not been contoured or regraded; heavy rutting and annual weedy vegetation observed.

Inspection Photos
Location Name: EVANS #11-2-1
Location ID: 337340



Photo 3. Taken from access road as it turns west towards location. Road has not been contoured or regraded; desirable vegetation observed along this portion of access road (e.g. blue grama, buffalo grass, sand drop seed, etc).

Inspection Photos
Location Name: EVANS #11-2-1
Location ID: 337340



Photo 4. Taken east of location, facing west. Photo illustrates location has not been reclaimed with presence of annual weedy vegetation and soil/dirt that has not been contoured or regraded to reflect reference areas.

Inspection Photos
Location Name: EVANS #11-2-1
Location ID: 337340



Photo 5. Facing north, see comments in photo 4.

Inspection Photos
Location Name: EVANS #11-2-1
Location ID: 337340



Photo 6. Facing south, see comments in photo 4.

Inspection Photos
Location Name: EVANS #11-2-1
Location ID: 337340



Photo 7. Close up photo showing gravel/road base still on location.

Inspection Photos
Location Name: EVANS #11-2-1
Location ID: 337340



Photo 8. Reference area photo taken south of location, facing south. Area is predominantly buffalo grass, sand drop seed, and blue grama.