

Final Reclamation and Stormwater Inspection

Date: 09/14/2022

Operator: PRIME OPERATING COMPANY - 72118

Location ID: 303467

Inspection Document #: 696105431

Yuma County, CO

SWSW Section 2 T5S R44W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: FLEER #13-2
Location ID: 303467



Photo 1. Taken from county road, facing northeast. Photo illustrates access road has not been reclaimed; annual weedy vegetation (predominantly russian thistle) present throughout access road and location.

Inspection Photos
Location Name: FLEER #13-2
Location ID: 303467



Photo 2. Access road, facing north. See comments in photo 1.

Inspection Photos
Location Name: FLEER #13-2
Location ID: 303467




Photo 3. Taken south of location, facing north. Photo illustrates access road and location have not been reclaimed with presence of annual weedy vegetation, access road and location which have not been contoured, regraded, or revegetated. Oil and gas equipment remain on location.

Inspection Photos
Location Name: FLEER #13-2
Location ID: 303467



Photo 4. Facing northwest, see comments in photo 3.

Inspection Photos
Location Name: FLEER #13-2
Location ID: 303467



Photo 5. Taken northwest of meter shed, facing west. Unknown buried container.