

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/13/2022

Submitted Date:

09/14/2022

Document Number:

690203402

FIELD INSPECTION FORMLoc ID 321045 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10626

Name of Operator: DOVER ATWOOD CORPORATION

Address: 1875 HARSH AVENUE SE

City: MASSILLON State: OH Zip: 44646

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

5 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
LEVENGOOD SARAH		doveratwoodcorp@yahoo.com	
Levengood, John		jlevengood07@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205853	WELL	PR	05/01/2020	GW	009-06268	ROBBINS RANCH 'C' 1	RI
480585	TANK BATTERY	AC	08/26/2021		-	Robbins Ranch Tank	RI

General Comment:

This is a follow up reclamation inspection of the tank battery site.
See attached photos and additional details within this report.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign does not reflect current Operator or emergency contact INFO. Wellhead was not inspected due to crop cover. Previous corrective action remains.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	06/09/2022
Type	BATTERY		
Comment:	Sign does not reflect current Operator or emergency contact INFO. Sign not posted or information inaccurate at battery. Previous corrective action not completed.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	06/09/2022

Emergency Contact Number:

Comment:	The emergency contact number was not valid.		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:	There is weed debris around the equipment which needs to be removed.		
Corrective Action:	Comply with Rule 610. Comply with Rule 606.	Date:	05/13/2022
Type	UNUSED EQUIPMENT		
Comment:	Tank is labeled NOT IN USE. All unused equipment needs to be removed.		
Corrective Action:	Comply with Rule 606.	Date:	06/09/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: Previous leak observed appears to be an irrigation line.

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
	1	100 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

	Inadequate			Inadequate	
Comment:	The berm around the tank is inadequate to contain a spill. The tank needs to be removed if not in use or the berm around the tank needs to be repaired. Previous corrective action not completed.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date:	06/09/2022

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403166685	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5860795
690203403	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5860754