

Final Reclamation and Stormwater Inspection

Date: 09/14/2022

Operator: ENERGY QUEST II LLC - 10490

Location ID: 337054

Inspection Document #: 696105434

Yuma County, CO

SENW Section 10 T5S R44W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BRENNER #10-6
Location ID: 337054



Photo 1. Taken from southern portion of location, facing north. Photo illustrates location has not been reclaimed with presence of annual weedy vegetation (russian thistle), non-uniform vegetation cover resulting in bare soil, and gully erosion on the east side of location (outlined in red).

Inspection Photos
Location Name: BRENNER #10-6
Location ID: 337054



Photo 2. Taken from northern tank battery location, facing southeast. See comments in photo 1.

Inspection Photos
Location Name: BRENNER #10-6
Location ID: 337054



Photo 3. Taken from eastern portion of location, facing east. Photo illustrates gully erosion approximately 1.5' deep x 115' length x 10' wide. Extent of erosion is leaving permitted location and contributing to offsite sediment deposition; no erosion control BMPs observed during inspection.

Inspection Photos
Location Name: BRENNER #10-6
Location ID: 337054



Photo 4. Taken from middle portion, east of location, facing west. See comments in photo 3.

Inspection Photos
Location Name: BRENNER #10-6
Location ID: 337054



Photo 5. Taken east of location, facing west. See comments in photo 3.

Inspection Photos
Location Name: BRENNER #10-6
Location ID: 337054



Photo 6. Reference area photo taken northeast of location, facing northeast. Predominantly buffalo grass and sand drop seed, among other desirable vegetation.