

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/13/2022

Submitted Date:

09/15/2022

Document Number:

690203410

FIELD INSPECTION FORM

Loc ID 320982 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10626
Name of Operator: DOVER ATWOOD CORPORATION
Address: 1875 HARSH AVENUE SE
City: MASSILLON State: OH Zip: 44646

Findings:

- 7 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
GEORGE KELLY		envexbaca@aol.com	
COGCC Enforcement		dnr_cogccenforcement@state.co.us	
Levengood, John		jlevengood07@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205671	WELL	PR	12/17/2012	GW	009-06082	BISHOP, E 1-29	RI

General Comment:

This is a follow up of the previous inspections; #690201497, #690201703, #690202890.
The previous inspection corrective actions have not been completed.
Non-compliance with the Rules will be referred to enforcement.
See attached photos and additional details within this report.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	The tank label does not comply with 605. Missing tank NFPA labeling and missing INFO. Previous corrective action not completed.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	07/23/2021

Emergency Contact Number:

Comment:	Sign posted at well site however emergency contact number is not correct. Previous corrective action not completed.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	07/23/2021

Good Housekeeping:

Type	DEBRIS		
Comment:	The door on the meter shed is laying on the ground and the meter shed is in disrepair.		
Corrective Action:	Comply with Rule 606	Date:	05/13/2022
Type	UNUSED EQUIPMENT		
Comment:	If the tank is not in use it needs to be removed. The tank contains a solidified substance that is half full.		
Corrective Action:	Comply with Rule 606	Date:	12/10/2021

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		37.318570,-102.284340
Comment:	There is an open top fiberglass tank at the location. The netting on the tank is in disrepair. The tank contains a solidified substance that is half full. Previous corrective action not completed				
Corrective Action:	Install or repair wildlife protection equipment.				Date: 05/13/2021

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
	Inadequate			Inadequate
Comment:	There is inadequate secondary containment around the tank. Previous corrective action not completed.			

Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).	Date:	06/03/2021
--------------------	--	-------	------------

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403167783	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5861600
690203411	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5861594