

Inspection Photos

Location Name: CAERUS PICEANCE LLC SPECIALITY RESTAURANT-68S96W /7LOT 2

Location ID: 334188



Photo #7755 From entrance to location.



Photo #7756 From entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC SPECIALITY RESTAURANT-68S96W /7LOT 2

Location ID: 334188



Photo #7757 From entrance to location.



Photo #7758 From entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC SPECIALITY RESTAURANT-68S96W /7LOT 2

Location ID: 334188



Photo #7759 Rill erosion.



Photo #7760 Rill erosion.

Inspection Photos

Location Name: CAERUS PICEANCE LLC SPECIALITY RESTAURANT-68S96W /7LOT 2

Location ID: 334188



Photo #7761 Gully erosion.



Photo #7762 Sediment trap is full run off of location is not being controlled.

Inspection Photos

Location Name: CAERUS PICEANCE LLC SPECIALITY RESTAURANT-68S96W /7LOT 2

Location ID: 334188



Photo #7763 Culvert capacity has been reduced due to Sediment migration.



Photo #7767 Rill erosion.