

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403170654

Date Received:
09/19/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10766
Name of Operator: ARKOMA OPERATIONS LLC
Address: 2121 S COLUMBIA AVE SUITE 101
City: TULSA State: OK Zip: 74114

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Price, Andrew</u>	<u>918-260-8324</u>	<u>aprice@arkomaops.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500437
Inspection Date: 09/13/2022 FIR Submit Date: 09/13/2022 FIR Status: _____

Inspected Operator Information:

Company Name: ARKOMA OPERATIONS LLC Company Number: 10766
Address: 2121 S COLUMBIA AVE SUITE 101
City: TULSA State: OK Zip: 74114

LOCATION - Location ID: 311913

Location Name: IGS Number: 419 County: LA PLATA
Qtrqr: NENW Sec: 21 Twp: 33N Range: 8W Meridian: N
Latitude: 37.093810 Longitude: -107.726180

FACILITY - API Number: 05-067-00 Facility ID: 216289

Facility Name: HERRERA GAS UNIT B Number: 5
Qtrqr: NENW Sec: 21 Twp: 33N Range: 8W Meridian: N
Latitude: 37.093810 Longitude: -107.726180

CORRECTIVE ACTIONS:

1 CA# 164536

Corrective Action: Install sign to comply with Rule 605.h. Date: 11/13/2022

Response: CA COMPLETED Date of Completion: 09/15/2022

Operator Comment: Produced water tank sign bad. Removed old sign and replaced with a new sign.

COGCC Decision: Approved pending re-inspection

CA from previous inspection Doc# 702500437 has been satisfactorily completed.

COGCC
Representative:

2 CA# 164537

Corrective Action: Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.

Date: 09/29/2022

Response: CA COMPLETED

Date of Completion: 09/15/2022

Operator Comment: At the IGS 115 pumping unit there is a impacted of surface material at the wellhead and on the eastside of the pumping unit.
Remove surface material at the wellhead and on the eastside of the pumping unit. Also put soaker pads down to stop material from hitting to ground.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500437 has been satisfactorily completed.

3 CA# 164538

Corrective Action: Install or repair/modify required BMPs per Rule 1002.f.(2)C

Date: 10/13/2022

Response: CA COMPLETED

Date of Completion: 09/15/2022

Operator Comment: A erosion channel formed at the cattle guard where the access road meets the location. We cleaned up area, put in some material, and put in rock dams down the road to slow the stormwater.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500437 has been satisfactorily completed.

OPERATOR COMMENT AND SUBMITTAL

Comment: See attached spreadsheet for detail on actions taken.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed: _____

Title: Engineering Analyst

Date: 9/19/2022 1:51:17 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403170654	FIR RESOLUTION SUBMITTED
403170658	Location 311913 Remedial Report

Total Attach: 2 Files