

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/16/2022

Submitted Date:

09/21/2022

Document Number:

688313149

FIELD INSPECTION FORMLoc ID 456540 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 1801 CALIFORNIA STREET #2500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

20 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Civitas		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456542	WELL	PR	11/06/2019	OW	005-07381	Prosper Farms 4-65 11-12 3DH	PR
456544	WELL	PR	11/06/2019	OW	005-07382	Prosper Farms 4-65 11-12 3CH	PR
456548	WELL	PR	11/06/2019	OW	005-07383	Prosper Farms 4-65 11-12 3AH	PR
456549	WELL	PR	11/06/2019	OW	005-07384	Prosper Farms 4-65 11-12 3BH	PR

General Comment:

Routine Field Inspection

Erosion at entrance, no sign at tank battery, missing bullplugs/caps on loadouts, VRU mechanical conditions, trash and checked 3BH bradenhead (and all bradenheads). See attached photos.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	no sign		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	10/21/2022
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	4		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 720-659-7400

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	outer and inner fencing		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flow Line	# 4		
Comment:	4 buried flow lines from wells to separators marked with white and yellow posts		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	3AH 6 psi 3BH 22 psi 3CH -3 psi 3DH -2 psi		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	not on		

Corrective Action:		Date:	
Type: Other	# 3		
Comment:	3 environmental monitors (see attached photos)		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	current calibration card		
Corrective Action:		Date:	
Type: VRU	# 2		
Comment:	one unit is leaking inside the container, fix mechanical conditions		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: FWKO	# 3		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:	Fix hole in netting under fuel tank at compressor (see attached photo).		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Flare	# 1		
Comment:	pilot on		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:		same metal berms as crude oil tanks					
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	7	500 BBLs	STEEL AST				
Comment:		check bullplugs/caps on loadouts, PCCs are in containment					
Corrective Action:						Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

Wells Served By Facilities Above**AirsID**

API Number
005-07381
005-07383
005-07384
005-07382

API Number	AirsID
------------	--------

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	456542	Type:	WELL	API Number:	005-07381	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	pr 6/1/2022 production is reported to COGCC database								
Corrective Action:							Date:		
Facility ID:	456544	Type:	WELL	API Number:	005-07382	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	pr 6/1/2022 production is reported to COGCC database								
Corrective Action:							Date:		
Facility ID:	456548	Type:	WELL	API Number:	005-07383	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	pr 6/1/2022 production reported to COGCC database								
Corrective Action:							Date:		
Facility ID:	456549	Type:	WELL	API Number:	005-07384	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	pr 6/1/2022 production reported to COGCC database								
Corrective Action:							Date:		

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Gravel	Pass	Gravel	Pass			
Waddles	Pass	Waddles	Pass			
Compaction	In Process	Compaction	Pass			

Comment: [Erosion around culvert at entrance \(see attached photos\).](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403172832	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5865742
688313155	Crestone Prosper Farms 4 -65 11-12 4 well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5865740