

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/21/2022

Submitted Date:

09/21/2022

Document Number:

702500459**FIELD INSPECTION FORM**
 Loc ID 326237 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10766Name of Operator: ARKOMA OPERATIONS LLCAddress: 2121 S COLUMBIA AVE SUITE 101City: TULSA State: OK Zip: 74114**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		SJBcompliance@arkomaops.com	ALL SW field inspections
Price, Andrew	918-260-8324	aprice@arkomaops.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216086	WELL	PR	08/01/2018	CBM	067-07692	JAQUES 6-F	PR
454845	WELL	PR	08/16/2018	CBM	067-10018	Jaques 12	PR
454846	WELL	PR	08/16/2018	CBM	067-10019	Jaques 11	PR
454847	WELL	PR	08/16/2018	CBM	067-10020	Jaques 10	WK

General Comment:

Inspector Alex Klink on site to conduct routine inspection and observe workover operations. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Flow Line

15

Comment: 7 3" lines from wellheads to separators, 4 3" lines from separators to gas meter run, 4 2" lines from separators to produced water.

Corrective Action: Date:

Type: Ancillary equipment

7

Comment: Telemetry, electric meter, electric panels, 4 pump control panels

Corrective Action: Date:

Type: Pump Jack

3

Comment: Corrective Action: Date:

Type: Other

1

Comment: Linear rod pump

Corrective Action: Date:

Type: Vertical Heated Separator

4

Comment: Corrective Action: Date:

Type: Prime Mover

4

Comment: Electric

Corrective Action: Date:

Type: Pump Jack

3

Comment: Corrective Action: Date:

Type: Gas Meter Run

4

Comment: Gas meter calibrations are within the last year.

Corrective Action: Date:

Type: Bird Protectors

5

Comment: Separator vent stacks are screened properly

Corrective Action: Date:

Type: Bradenhead	# 4	
Comment:	Bradenheads are accessible.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	STEEL AST		37.071581,-107.700576
Comment:	2 above ground produced water tanks each with 500 bbl capacity.				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)	cone top	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Earth berm with liner			
Corrective Action:			Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 216086 Type: WELL API Number: 067-07692 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 454845 Type: WELL API Number: 067-10018 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 454846 Type: WELL API Number: 067-10019 Status: PR Insp. Status: PRFacility ID: 454847 Type: WELL API Number: 067-10020 Status: PR Insp. Status: WK**Workover**Comment: Workover rig on location to repair damaged rod.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Berms	Fail					run off berm
Rip Rap	Pass					
Berms	Pass					Run on berm
Ditches	Pass					
		Compaction	Pass			
		Gravel	Pass			
Gravel	Pass					

Comment: Stormwater channel has formed on fill slope on eastern edge of location (IMG 03).
Stormwater has impacted run off berm and eroded a hole through it (04).

Facilities must be operated in a manner that minimizes erosion, transport of sediment
offsite, and site degradation.

Corrective Action: **Install or repair/modify required BMPs per Rule 1002.f.(2)C**

Date: 10/07/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403173781	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5866401
702500460	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5866394