

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/27/2022

Submitted Date:

09/29/2022

Document Number:

689501417

**FIELD INSPECTION FORM**

Loc ID 410066 Inspector Name: Brown, Kari On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 47120  
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
 Address: P O BOX 173779  
 City: DENVER State: CO Zip: 80217-

**Findings:**

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Hamilton, Greg		Gregory_Hamilton@oxy.com	<a href="#">Oxy Environmental</a>
,		COGCCInspections@Oxy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
482762	SPILL OR RELEASE	CL	08/12/2022		-	Varra 10-2 Flowline	EI

**General Comment:**

This is an environmental inspection of Spill ID 482762 (CL)/Remediation Project No 24096. Any corrective actions from previous inspections that have not been addressed are still applicable.

[Photo attached to document site conditions.](#)

**Inspected Facilities**

Facility ID: 482762 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: A shallow excavation was open at the time of inspection with flowline ends exposed. Groundwater was observed in the open excavation. Excavation area was surrounded by orange snow fencing.

Corrective Action:  Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)	
Comment	Soil was stored on location with earthen berms. Earthen berms did not completely surround the soils pile.				
Corrective Action	Manage soils in compliance with Rule 913.b.iv and COGCC Guidance 913.b.(5)B i-v.				Date: <u>10/13/2022</u>

**Spill/Remediation:**

Comment:

Corrective Action:  Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689501418	Open excavation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874124">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874124</a>
689501419	Fencing	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874125">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874125</a>
689501420	Soils pile	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874126">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874126</a>