

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/23/2022

Submitted Date:

09/23/2022

Document Number:

702500471**FIELD INSPECTION FORM**Loc ID 307028 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW field inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299998	WELL	PA	12/04/2008	OTH	067-09650	PHILLIPS GU A 3	PA
414635	WELL	DA	04/17/2015	DA	067-09799	Phillips A 3R	DA
441563	WELL	PR	07/16/2021	GW	067-09931	PHILLIPS A 3R2	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds at produced water tank (IMG 04).		
Corrective Action:	Ensure within 25' of wellhead, tanks, and separators are free of combustible material per rule 610.k	Date:	10/08/2022
Type	STORAGE OF SUPL		
Comment:	Unused 4" pipe near gas meter run (IMG 05).		
Corrective Action:	All unused equipment must be returned to use or stored off location per rule 606.	Date:	10/08/2022
Type	OTHER		
Comment:	Lube oil at A 3R2 wellhead has impacted surface material (IMG 03).		
Corrective Action:	Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.	Date:	10/08/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Location enclosed by wire fencing.		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 2		corrective date
Comment:	Bradenheads are accessible.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 2	
Comment:	Gas meter calibrations are within the last year.	
Corrective Action:		Date:
Type: Ancillary equipment	# 6	
Comment:	Telemetry, electric cabinet, 2 pump control panels, 2 valve cluster pits	
Corrective Action:		Date:
Type: Prime Mover	# 2	
Comment:	Electric	
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:	Separator vent stacks are screened properly	
Corrective Action:		Date:
Type: Flow Line	# 6	
Comment:	2 3" and 2 2" lines from wellheads to separators, 2 2" lines from separators to produced water.	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.145397,-107.826275
Comment:	Partially buried produced water tank.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	95 bbl
Other (Type)	cone top

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 299998 Type: WELL API Number: 067-09650 Status: PA Insp. Status: PAFacility ID: 414635 Type: WELL API Number: 067-09799 Status: DA Insp. Status: DAFacility ID: 441563 Type: WELL API Number: 067-09931 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Compaction	Pass					
		Compaction	Pass			
		Gravel	Pass			
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403176884	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5868825">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5868825</a>
702500472	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5868818">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5868818</a>