

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/29/2022

Submitted Date:

09/29/2022

Document Number:

702500519

FIELD INSPECTION FORM
 Loc ID 378719 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 69805

Name of Operator: PETROX RESOURCES INC

Address: 12600 W COLFAX AVENUE #C-440

City: LAKEWOOD State: CO Zip: 80215

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Nystrom, Dusty	(505) 330-1328/ (719) 529-0682	nystwr@yahoo.com	All SW field inspections
Clark, Ryan		ryan@petrox-resources.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
302120	WELL	PR	06/01/2020	CBM	007-06278	CANDELARIA 33-5 10-1	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank is not labeled for capacity or contents (IMG 06).		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	11/29/2022

Emergency Contact Number:		
Comment:	<div style="border: 1px solid black; height: 20px;"></div>	
Corrective Action:	<div style="border: 1px solid black; height: 20px;"></div>	Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Pump jack belt guard (IMG 04) is not in use. Transducer, pressure gauge, valve handle, and misc equipment at separator are unused (IMG 05), and enclosure is not in use (IMG 07).		
Corrective Action:	All unused equipment must be returned to use or stored off location per rule 606.	Date:	10/29/2022
Type	OTHER		
Comment:	Lube oil has impacted surface material at wellhead (IMG 03).		
Corrective Action:	Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.	Date:	10/14/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:	Separator vent stack is screened properly		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration is within the last year.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Pump jack on elevated platform		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:		Date:	

Type: Flow Line	# 3	
Comment:	2" line from wellhead to separator, line from separator to produced water, 2" line from separator to gas powered prime mover.	
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	Gas powered	
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Telemetry	
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		Open Top		37.125701,-107.380559
Comment:	Above ground produced water tank with steel mesh screen top.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 302120	Type: WELL	API Number: 007-06278	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
				Material Handling And Spill Prevention	Pass	
Gravel	Pass					
		Gravel	Pass			
Compaction	Pass					
		Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500520	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874430