

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/05/2022

Submitted Date:

10/05/2022

Document Number:

699106108

**FIELD INSPECTION FORM**
 Loc ID 441915 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name | Phone | Email                         | Comment                         |
|--------------|-------|-------------------------------|---------------------------------|
| ,            |       | Inspections@civiresources.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name              | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------------|-------------|
| 442470      | WELL | PR     | 11/26/2015  | OW         | 123-41887 | North Platte K31-O34-34HNB | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             |          |       |  |
| Corrective Action:   |          | Date: |  |

|                           |          |  |             |
|---------------------------|----------|--|-------------|
| Emergency Contact Number: |          |  |             |
| Comment:                  | Adequate |  |             |
| Corrective Action:        |          |  | Date: _____ |

|                           |  |  |                  |
|---------------------------|--|--|------------------|
| <b>Good Housekeeping:</b> |  |  |                  |
| Type                      | OTHER  |  |                  |
| Comment:                  | Stained soil next to the well needs to be removed. See attached photo. |  |                  |
| Corrective Action:        | . "Properly dispose of oily waste in accordance with 905.e."           |  | Date: 10/14/2022 |

Overall Good: ☐

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

|                    |          |       |  |
|--------------------|----------|-------|--|
| <b>Fencing/:</b>   |          |       |  |
| Type               | WELLHEAD |       |  |
| Comment:           | Panel    |       |  |
| Corrective Action: |          | Date: |  |

|                    |  |       |                  |
|--------------------|--|-------|------------------|
| <b>Equipment:</b>  |  |       | corrective date  |
| Type: Plunger Lift | # 1  |       |                  |
| Comment:           |  |       |                  |
| Corrective Action: |  | Date: |                  |
| Type: Bradenhead   | # 1  |       |                  |
| Comment:           | Appears to be plumbed to surface   |       |                  |
| Corrective Action: |  | Date: |                  |
| Type: Other        | # 1  |       |                  |
| Comment:           | Master valve appears to be leaking fix or replace. See attached photo.   |       |                  |
| Corrective Action: | Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. |       | Date: 10/14/2022 |

|                    |    |       |  |
|--------------------|----|-------|--|
| <b>Venting:</b>    |    |       |  |
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                 |  |  |  |
|-----------------|--|--|--|
| <b>Flaring:</b> |  |  |  |
|-----------------|--|--|--|

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 442470 Type: WELL API Number: 123-41887 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/04/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Wednesday 10/5/22 at approximately 0835hrs, I, Inspector Adam Burns, Conducted an on-site inspection at North Platte K31-O34-34HNB of Civitas, at API # 05-123-41887 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil next to the well needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 10/14/22.</p> <p>Master valve appears to be leaking fix or replace. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a corrective action date of 10/14/22.</p> <p>See attached photo.</p> <p>Submit pictures on FIRR.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | burnsa | 10/05/2022 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 699106109    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5879044">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5879044</a> |