

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/27/2022

Submitted Date:

09/29/2022

Document Number:

689501417

FIELD INSPECTION FORMLoc ID 410066 Inspector Name: Brown, Kari On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hamilton, Greg		Gregory_Hamilton@oxy.com	Oxy Environmental
,		COGCCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
482762	SPILL OR RELEASE	CL	08/12/2022		-	Varra 10-2 Flowline	EI

General Comment:

This is an environmental inspection of Spill ID 482762 (CL)/Remediation Project No 24096. Any corrective actions from previous inspections that have not been addressed are still applicable.

Photo attached to document site conditions.

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: A shallow excavation was open at the time of inspection with flowline ends exposed. Groundwater was observed in the open excavation. Excavation area was surrounded by orange snow fencing.

Corrective Action: _____

Date: _____

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____

Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Comment	Soil was stored on location with earthen berms. Earthen berms did not completely surround the soils pile.			
Corrective Action	Manage soils in compliance with Rule 913.b.iv and COGCC Guidance 913.b.(5)B i-v.			Date: 10/13/2022

Type	Management	Condition	GPS (Lat)	(Long)
Comment	Soil was stored on location with earthen berms. Earthen berms did not completely surround the soils pile.			
Corrective Action	Manage soils in compliance with Rule 913.b.iv and COGCC Guidance 913.b.(5)B i-v.			Date: 10/13/2022

Spill/Remediation:

Comment: _____

Corrective Action: _____

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403182755	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874133
689501418	Open excavation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874124
689501419	Fencing	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874125
689501420	Soils pile	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874126