

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY-66S92W /30NWSE

Location ID: 335358



Photo #7907 From entrance to location.



Photo #7908 From entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY-66S92W /30NWSE

Location ID: 335358



Photo #7910 Location lacks stabilization.



Photo #7911 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY-66S92W /30NWSE

Location ID: 335358



Photo #7912 Location lacks stabilization.



Photo #7913 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY-66S92W /30NWSE

Location ID: 335358



Photo #7915 insufficient tracking BMP's at entrance to location.