

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY-66S92W /32NWNW

Location ID: 335301



Photo #7915 From entrance to location.



Photo #7916 From entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY-66S92W /32NWNW

Location ID: 335301



Photo #7917 From entrance to location.



Photo #7918 Chemical tank missing required information.

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY-66S92W /32NWNW

Location ID: 335301



Photo #7923 Stained soils in containment.



Photo #7919 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY-66S92W /32NWNW

Location ID: 335301



Photo #7920 Location lacks stabilization.



Photo #7224 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY-66S92W /32NWNW

Location ID: 335301



Photo #7925 Insufficient tracking BMP at entrance to location.