

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/04/2022

Submitted Date:

10/05/2022

Document Number:

699805007

FIELD INSPECTION FORMLoc ID 335358 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

22 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261630	WELL	PR	06/04/2002	GW	045-07970	COUEY 30-10A1 (O30NE)	PR
272414	WELL	PR	12/02/2004	GW	045-10075	COUEY 30-9 (O30NE)	PR
273477	WELL	PR	11/04/2004	GW	045-10252	COUEY 30-16 (O30NE)	PR
282075	WELL	PR	06/12/2006	GW	045-11619	COUEY 30-9C (O30NE)	PR
282076	WELL	PR	06/12/2006	GW	045-11618	COUEY 30-15B (O30NE)	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 10/4/22 at approximately 11:00 hours, I, Inspector Corey De Paolo,
Conducted an on-site inspection at CAERUS PICEANCE LLC COUEY-66S92W /30NWSE.
Location #335358 in Garfield County Colorado.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1) Location lacks stabilization. Insufficient tracking BMP at entrance to location with a corrective action date of 10/19/22.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the
Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed wire fence around location		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 5		
Comment:	Pressure transducers located on braden head. All braden head valves are accessible.		
Corrective Action:		Date:	

Type: Gas Meter Run	# 5	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 5	
Comment:	All wells on plunger lift	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:	Summit midstream	
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Vertical Heated Separator	# 5	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Centralized containment				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	Centralized containment				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	500 BBLs	HEATED STEEL AST		,	

Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	Centralized containment				
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
Date:			

Flaring:

Type			
Comment:			
Corrective Action:			
Date:			

Inspected Facilities				
Facility ID: <u>261630</u>	Type: <u>WELL</u>	API Number: <u>045-07970</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing</u>				
Corrective Action:				Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>
Facility ID: <u>272414</u>	Type: <u>WELL</u>	API Number: <u>045-10075</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing</u>				
Corrective Action:				Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>
Facility ID: <u>273477</u>	Type: <u>WELL</u>	API Number: <u>045-10252</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing</u>				
Corrective Action:				Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>
Facility ID: <u>282075</u>	Type: <u>WELL</u>	API Number: <u>045-11619</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing</u>				
Corrective Action:				Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>
Facility ID: <u>282076</u>	Type: <u>WELL</u>	API Number: <u>045-11618</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing</u>				
Corrective Action:				Date: <div style="border: 1px solid black; width: 100px; height: 20px;"></div>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Berms						
Ditches						
		Compaction				
Sediment Traps						
Gravel						Gravel insufficient
Other						Insufficient tracking BMP at entrance to location.
		Berms				
Compaction						Location lacks stabilization
		Sediment Traps				
		Culverts				
		Ditches				

Comment: [Location lacks stabilization. Insufficient tracking BMP at entrance to location.](#)Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations](#)

Date: 10/19/2022

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Refer to Storm water for corrective actions.	depaoloc	10/04/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805008	Photos for Insp. #699805007	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5880803