

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2022

Submitted Date:

10/06/2022

Document Number:

699805011

FIELD INSPECTION FORMLoc ID 335400 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

16 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258231	WELL	PR	02/01/2022	GW	045-07627	COUEY 32-4(D32NE)	PR
258232	WELL	PR	02/01/2022	GW	045-07628	COUEY 31-1(D32NE)	PR
258233	WELL	SI	07/01/2022	GW	045-07629	SHIDELER 32-3(D32NE)	SI
258234	WELL	PR	02/01/2022	GW	045-07630	COUEY 32-5(D32NE)	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 10/4/22 at approximately 13:00 hours, I, Inspector Corey De Paolo,
Conducted an on-site inspection at CAERUS PICEANCE LLC COUEY-66S92W /32NWNW.
Location #335400 in Garfield County Colorado.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1) Undesirable plant species in tank containment with a corrective action date of 10/11/22.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the
Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Undesirable plant species in tank containment.		
Corrective Action:	Oil and Gas Locations will be kept free of all Undesirable Plant Species.	Date:	10/11/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit midstream		

Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	Pressure transducers located on braden head. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	Centralized containment		
Corrective Action:		Date:	
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 258231 Type: WELL API Number: 045-07627 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 258232 Type: WELL API Number: 045-07628 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 258233 Type: WELL API Number: 045-07629 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Last produced June 2022

Corrective Action:

Date: _____

Facility ID: 258234 Type: WELL API Number: 045-07630 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams				
		Compaction				
		Culverts				
		Gravel				
		Sediment Traps				
		Berms				
		Ditches				
Sediment Traps						
Compaction						
Ditches						
Gravel						
Berms						

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to housekeeping for corrective actions.	depaoloc	10/05/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699805012	Photos for Insp. #699805011	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5880805