

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/06/2022

Submitted Date:

10/07/2022

Document Number:

696204172

FIELD INSPECTION FORM

Loc ID 383009 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100185

Name of Operator: ENCANA OIL & GAS (USA) INC

Address: 370 17TH ST STE 1700

City: DENVER State: CO Zip: 80202-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Encana		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
383009	LOCATION	AL			-	Cedar Bench K29 6100	RI
428942	WELL	AL	10/02/2014	LO	045-21491	CB DHS5B-32K296100	AL
428943	WELL	AL	10/02/2014	LO	045-21492	CB DHN1B-20K296100	AL
428944	WELL	AL	10/02/2014	LO	045-21493	CB DHN5B-20K296100	AL
428945	WELL	AL	10/02/2014	LO	045-21494	CB DHN7B-20K296100	AL
428946	WELL	AL	10/02/2014	LO	045-21495	CB DHS7B-32K296100	AL
428947	WELL	AL	10/02/2014	LO	045-21496	CB DHN3B-20K296100	AL

General Comment:

On 10/7/2022, Reclamation Specialist Trujillo conducted a Final Reclamation inspection at Encanas Cedar Bench 529 6100 location in Garfield County, Colorado.

Refer to the "Reclamation" sections of this inspection report for additional details.

Inspected Facilities

Facility ID: <u>383009</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AL</u>	Insp. Status: <u>RI</u>
Facility ID: <u>428942</u>	Type: <u>WELL</u>	API Number: <u>045-21491</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>428943</u>	Type: <u>WELL</u>	API Number: <u>045-21492</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>428944</u>	Type: <u>WELL</u>	API Number: <u>045-21493</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>428945</u>	Type: <u>WELL</u>	API Number: <u>045-21494</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>428946</u>	Type: <u>WELL</u>	API Number: <u>045-21495</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>428947</u>	Type: <u>WELL</u>	API Number: <u>045-21496</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Records and historic imagery shows Location was constructed and a well drilled under North American Resources Company; well was DA 1994 and received a passing reclamation inspection in 2009.

In 2012, the Location and additional wells were permitted under Encana. In 2014, Operator submitted Form 4s (e.g. 400700210) to abandon both the wells and Location; wells not drilled, Location not constructed.

Though location was constructed, all disturbances observed are related to the original pad construction under North American Resources Company, and no additional disturbances were created while Location was under Encana's ownership, as indicated within the Form 4s to abandon the permits.

Corrective Action:

Date

Overall Final Reclamation

Pass

Well Release on Active Location ☐Multi-Well Location ☐**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696204173	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5880888