

Inspection Photos

API: 055-06067

Operator: OXY USA INC

Inspection Date: 10/6/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06067 | Date: 10/6/2022

Inspection Photos



Photo 1. Facing north along the access road. The disturbance from the flowline along the road needs to be reclaimed and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06067 | Date: 10/6/2022

Inspection Photos



Photo 2. The disturbance from the flowline along the road needs to be reclaimed and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06067 | Date: 10/6/2022

Inspection Photos



Photo 3. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06067 | Date: 10/6/2022