

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/03/2022

Submitted Date:

10/07/2022

Document Number:

700300464

FIELD INSPECTION FORM

Loc ID 333435 Inspector Name: LABOWSKIE, STEVE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|---------------------------|--|
| Harrison, Trish | 970 759 9545 | trishharrison@eis-llc.com | All SW field inspections |
| Overright, Issac | | ioverright@maralexinc.com | All SW field inspections |
| , | 970-563-4000 | maralextech@gmail.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------|-------------|
| 267697 | WELL | PR | 08/10/2003 | CBM | 067-08803 | KATIE EILEEN 34-7-35 2A | PR |
| 290230 | WELL | PR | 04/17/2007 | CBM | 067-09352 | KATIE EILEEN 34-7-35 4 | PR |

General Comment:

Workover rig with tubing in derrick observed from public roadway (see attachemnt section for link to photo). No Form electronic Form 42 notification received. Compliance supervisor waited for subsequent notice of unplanned operatiosn and no subsequent notice for unplanned operations have been received as of 13:00 hrs 10/7/22.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|----------------------|-------|----------------------|
| Yes/No | | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | | Date: | <input type="text"/> |

Flaring:

| | | |
|--------------------|----------------------|----------------------------|
| Type | | |
| Comment: | <input type="text"/> | |
| Corrective Action: | | Date: <input type="text"/> |

Inspected Facilities

Facility ID: 267697 Type: WELL API Number: 067-08803 Status: PR Insp. Status: PR

Facility ID: 290230 Type: WELL API Number: 067-09352 Status: PR Insp. Status: PR

Workover

Comment: Rig observed up on location with tubing in derrick, no Form 42 notification for either well received as of 10/7/22

Corrective Action: Submit electronic Form 42 as required by rule 405.e for location ID# 333435 retroactively for the date rig was moved onto location (10/3/22 or before)

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 700300465 | picture from road of rig on location with tubing | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5881198 |