

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/07/2022

Submitted Date:

10/07/2022

Document Number:

702500577

FIELD INSPECTION FORM

Loc ID 334292 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 14 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260137	WELL	PR	04/13/2005	CBM	067-08484	DUSTIN 09-01 2	PR
298878	WELL	PR	10/09/2008	CBM	067-09637	DUSTIN 09-01 4	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

At time of inspection produced water was being released from #4 wellhead. A phone call was placed to Simcoe to notify of active release.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Produced water is being released at #4 wellhead. (IMG 03).		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	10/08/2022
Type	OTHER		
Comment:	Lube oil at #2 wellhead has impacted surface material (IMG 04).		
Corrective Action:	Remove impacted material from both wellheads and dispose of in approved manner per rule 906 and 1002.f.	Date:	10/22/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	Equipment on this location are enclosed by stock panel.		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Flow Line	# 5		
Comment:	2 3" and 2 2" lines from wellheads to separators, line from separatos to produced water		
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Linear rod pump		
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Electric		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Produced water tank vent is screened.		
Corrective Action:		Date:	

Type: Ancillary equipment	# 4	
Comment:	Telemetry, electric cabinet, 2 pump control panels,	
Corrective Action:		Date:
Type: Deadman # & Marked	# 6	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 2	
Comment:	Bradenheads are accessible.	
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:	Gas meter calibrations are within the last year.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.201055,-107.831002
Comment:	Partially buried double walled produced water tank				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	95 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Double walled			
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 260137 Type: WELL API Number: 067-08484 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 298878 Type: WELL API Number: 067-09637 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
		Gravel	Pass			
Gravel	Pass					
Compaction	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500578	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5881359