

# Inspection Photos

API: 055-06041

Operator: OXY USA INC

Inspection Date: 10/6/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06041 | Date: 10/6/2022

## Inspection Photos



**Photo 1.** Facing southwest along the access road near the SMU #1-12-B . There is sediment from the road depositing in this area. BMP's such as a sediment trap should be installed in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06041 | Date: 10/6/2022

## Inspection Photos



**Photo 2.** Facing southwest along the access road near the SMU #1-12-B . The road was graded along a portion of the road. The concern now is lack of BMP's on this long stretch or road which will direct stormwater and create more erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06041 | Date: 10/6/2022

## Inspection Photos



**Photo 3.** Facing northeast. The road will direct stormwater all the way down the road creating erosion. BMP's need to be installed to direct stormwater off the road and reduce stormwater concentration along the road. A diversion ditch would be helpful at the red arrow along with water bars, sediment traps, check dams, ect.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06041 | Date: 10/6/2022

## Inspection Photos



**Photo 4.** Facing southwest along the graded road. There are no BMP's installed along this portion of road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06041 | Date: 10/6/2022

## Inspection Photos



**Photo 5.** Facing southwest. The grading ended at this point which appears to be more stabilized with vegetation. Did not inspect any further due to wet soil conditions.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06041 | Date: 10/6/2022