

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/10/2022

Submitted Date:

10/10/2022

Document Number:

702401169**FIELD INSPECTION FORM**Loc ID 336471 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
,		rwatzman@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240718	WELL	PR	06/01/2022	GW	123-08506	FREDERICK 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	labels and placards faded and need to be replaced		
Corrective Action:	Comply with Rule 605.g	Date:	12/10/2022
Type	WELLHEAD		
Comment:	faded, peeling and needs to be replaced		
Corrective Action:	Comply with rule 605.g	Date:	12/10/2022

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	chainlink		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barb wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	barb wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		

Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment: electric motor			
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment: automation, electric panel, meter box and transformers			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment: cards indicate current calibration			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment: appears plumbed to surface			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.118660,-104.948070
Comment:					
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)	210 bbl				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares containment with crude tank					
Corrective Action:					Date:

Wells Served By Facilities AboveAirsID

API Number	API Number	AirsID
123-09243		
123-08506		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 240718 Type: WELL API Number: 123-08506 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 06/06/2022Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 10/10/2022 at approximately 1100 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:</p> <p>Operator: KP Kauffman</p> <p>Location: Fredrick #1</p> <p>API #05-123-08506</p> <p>County: Weld.</p> <p>While there, I observed a wellsite, PR at the time of inspection.</p> <p>During this inspection the following compliance issues were observed:</p> <p>605.g signs general condition: WH sign, Tank labels & placards ar faded/peeling and need to be replaced, CA dat 12-10-2022.</p> <p>Location is dry, weather is clear.</p> <p>A follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	10/10/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702401170	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5882533