

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/30/2022

Submitted Date:

10/04/2022

Document Number:

700300441

**FIELD INSPECTION FORM**

Loc ID 325310 Inspector Name: LABOWSKIE, STEVE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 31250  
Name of Operator: FRITZ & DIGMAN INC  
Address: PO BOX 70024  
City: ALBUQUERQUE State: NM Zip: 87197-

**Findings:**

- 9 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Andrews, Vern		vern@walsheng.net	
Digman, Rebecca	505-379-8689	rcdigman@yahoo.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214538	WELL	PR	12/01/2021	OW	067-06141	DAKOTA FEE 1	PR

**General Comment:**

Follow-up inspection, well shut in, no longer venting/flaring. FLIR video does show flowline at wellhead still leaking or leaking again. Weeds have grown up around equipment. No correctvie actions completed on access road, still no erosion control BMPs installed or repairs/mainenance done on access road, erosion and sediment migration have continued.

Form 1 still lists Rebecca Digman as principal agent and principal agent must be a recipient. Updating Form 1 information is responsibility of operator.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	appears gearbox is no longer leaking		
Corrective Action:		Date:	
Type	WEEDS		
Comment:			
Corrective Action:	remove weeds and all trash/combustible materials from around equipment and production area	Date:	10/12/2022
Type	UNUSED EQUIPMENT		
Comment:	appears parts and unuseable fittings have been rmeoved although difficult to fully see due to weed growth		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type	#	corrective date
Type: Pump Jack	#	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	#	
Comment:	wellhead	
Corrective Action:		Date:
Type: Prime Mover	#	
Comment:		
Corrective Action:		Date:
Type: Flow Line	# 2	
Comment:		
Corrective Action:		Date:
Type: Flare	# 1	

Comment:	fire tube combuster not in use at time of inspection		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Weeds growing tall inside containment berms			
Corrective Action:	Control weeds anmd maintain berms per Rules 606 and 605.a(4) (old rules)			Date: 10/19/2022

**Venting:**

Yes/No	NO	
Comment:	no longer venting/flaring through combuster tube	
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 214538 Type: WELL API Number: 067-06141 Status: PR Insp. Status: PR

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No action appears to have been taken on erosion on access road, no BMPOs present, no plan submitted. Visible erosion and sediment migration appear to have become worse. Erosion also occurring off ad and onto/along side access road.

Corrective Action: Immediately install erosion control BMPs and stabilize and repair access road. Also submit engineered plan by a erosion control supervisor or similar certified professional in order to comply with previous corrective actions (date retained) in regard to road design, stabilization and maintenance to comply with Rule 1002.f. Simply blading road has not worked in poast to achieve compliance.

Date: 05/31/2021

**Pits:**     NO SURFACE INDICATION OF PIT

