

**FORM
INSP**Rev
X/20

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/04/2022

Submitted Date:

10/04/2022

Document Number:

702500544

FIELD INSPECTION FORM
 Loc ID 320848 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1001 17TH STREET STE 1160

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, General		Inspections@catamountep.com	All SW field inspections
Telecky, Barbara		btelecky@blm.gov	Durango
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205218	WELL	TA	06/01/2021	CBM	007-06095	FEDERAL 26-1	TA

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

While accessing this location, several observations were made of stormwater impact along the access road. See below for a description and link at end of report for pictures. A collaborative effort should be made with the operator sharing this access road, Simcoe LLC, to repair these impacts. Erosion has exposed gathering pipeline along access road.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Other

1

Comment: Wellhead. Gas bubbles at bradenhead access (IMG 03, IMG 04).

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 11/05/2022**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 205218 Type: WELL API Number: 007-06095 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Last reported MIT: 11/13/2020

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Waddles	Pass					
Gravel	Pass					
		Culverts	Fail			
Berms	Pass					
Ditches	Fail					
Check Dams	Pass					
Compaction	Pass					

Comment: Ditch on eastern edge of location is filled with sediment, originating from cut slope. Ditch is unmaintained (IMG 05). Erosion channels off of access road. Access road is not maintained (IMG 06, IMG 08, IMG 09, IMG 11, IMG 12, IMG 14, IMG 15, IMG 17). Sediment on access road which appears to be originating from up gradient, culvert inlet is buried, plugged, and unmaintained (IMG 07, IMG 15, IMG 19). Ditch filled with sediment which appears to be originating from up gradient. Ditch is unmaintained (IMG 10, IMG 13, IMG 18). Culverts have no outlet protection and are unmaintained. (IMG 17, IMG 20). This inspection was conducted ~48 hours after storm event, which is the CDPHE required time for self inspection and response.

Corrective Action: Install or repair/modify required BMPs per Rule 1002.f.(2)C, including culverts and ditches in order to minimize and control erosion and sediment migration.

Date: 11/05/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403188846	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5879116
702500550	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5879105